



# Mod.2270 A


01.07.2009

9005 497  
9005 498/115V  
9005 947






**CROSS / CUT**  
3x25mm  
**Mod. 2270 A**  
 01.07.2009




CROSS / CUT 3x25mm  
**Mod. 2270 A**  
 01.07.2009




2250 020

9001 699




2250 605



2250 050

**Mod. 2270 A**  
CROSS / CUT 3x25mm  
01.07.2009



Anschlußplan 2270 A CROSS/CUT  
 Diagramme de branchement 2270 A CROSS/CUT  
 Connecting diagram 2270 A CROSS/CUT


2250 632  
 5

CROSS / CUT 3x25mm  
**Mod. 2270 A**  
 01.07.2009

Netz  
 Power Supply  
 Branchement  
 au Secteur


Motor  
 Motor  
 Moteur

Kondensator  
 Capacitor  
 Condensateur




**Mod. 2270 A**  
 CROSS / CUT 3x25mm  
 01.04.2012

Anschlußplan 2270 A CROSS/CUT  
 Diagramme de branchement 2270 A CROSS/CUT  
 Connecting diagram 2270 A CROSS/CUT



**Mod. 2270 A**  
 CROSS / CUT 3x25mm  
 01.07.2009

Stromlaufplan 2270 A CROSS/CUT  
 schema de circuit électrique 2270 A CROSS/CUT  
 wiring diagram 2270 A CROSS/CUT



**Mod. 2270 A**  
 CROSS / CUT 3x25mm  
 01.04.2012

Stromlaufplan 2270 A CROSS/CUT  
 schema de  
 circuit électrique 2270 A CROSS/CUT  
 wiring diagram 2270 A CROSS/CUT

2250 663