




**DIAMOND CORE
DRILLING MOTOR
PARTS LIST**

**MODEL
CB515**

JULY 2018



CB515 110V PARTS LIST JULY 2018

ITEM	PART NO	QTY	DESCRIPTION
1	6078402	1	PRCD ASM W/ CORD AND MOLDED PLUG
1-1	6078494	1	PWR SUPPLY CABLE W/ PLUG 15AMP
1-2	6078495	1	PRCD INTERRUPTER PROTECTION (110V)
2	2709133	1	POWER SUPPLY CABLE W/O PLUG
3	6078403	1	CORD ARMOR
4	2709136	1	CABLE CLIP
5	2709146	2	PANHEAD TAPPING SCREW-B (M4x14)
6	2709114	1	SWITCH 110V
7	2709115	1	TERMINAL CONNECTOR BLOCK
8	2709116	1	ELECTRONIC UNIT (110V)
9	2709117	1	HANDLE R-SIDE
10	2709118	1	HANDLE L-SIDE
11	2709119	5	PANHEAD TAPPING SCREW-B (M4x20)
12	2709120	3	PANHEAD TAPPING SCREW-B (M4x35)
13	2709121	4	TORX PANHEAD TAPPING SCREW-C (M5x20)
14	2709122	4	PANHEAD TAPPING SCREW-B (M4x8)
15	2709123	2	BRUSH SPRING
16	2709124	2	BRUSH HOLDER
17	2709125	2	INSULATION PLATE
18	6078414	2	CARBON BRUSH
19	2709013	3	PANHEAD MACHINE SCREW (M4x6xP0.7)
20	2709128	1	BUBBLE LEVEL
21	2709129	1	MOTOR HOUSING
22	2709130	1	STATOR 110V
23	2709131	2	PANHEAD TAPPING SCREW-A (3/16"x3")
24	2709132	1	FAN SHROUD
25	6078427	1	BALL BEARING (6200)
26	2709134	1	ARMATURE 110V
27	2709135	1	BALL BEARING (6201)
28	6078432	1	EXTERNAL STAR WASHER (M4)
29	2709137	1	EARTH WIRE (Ø3x200MM)
30	2709138	1	GEAR PLATE
31	2709139	1	GASKET
32	2709140	1	BALL BEARING (608)
33	2709141	1	CLUTCH NUT
35	2709142	1	PRESSURE DISC
37	2709143	1	INPUT GEAR
38	2709144	1	BUSHING
40	2709145	1	INPUT SHAFT

CB515 110V PARTS LIST JULY 2018

[illegible]