




Part numbers on following page.

IMPORTANT: THIS IS DATED INFORMATION. When requesting service or replacement parts for your appliance please provide model number and serial number. All parts listed in this manual may be ordered from an authorized dealer.



**Stocked
at Depot**

ITEM	DESCRIPTION	COMMENTS	PART NUMBER	
	Electric Log Assembly	No longer available	4030-095	
1	Heater Face Cover	No longer available	4030-100	
2	Upper Glass Retainer	No longer available	4030-146	
3	SILH Grate Assembly	No longer available	4030-025	
4	Ember Bed Glass Panel	No longer available	4030-803	
5	Flame Tray Support - LH	No longer available	4030-165	
6	Flame Tray Support - RH	No longer available	4030-166	
7	Rock Retainer	No longer available	4030-157	
8	Upper Face Panel	No longer available	4030-144	
9	Door Track, Bottom		SRV15425	
10	Door Pivot Clip	Qty. 2 req.	SRV31527	
11	Screen & Rod Assembly - 36 in.	No longer available	4030-033	
12	Screen Rod - 36 in. Electric	No longer available	4030-163	
13	Firescreen Assembly	No longer available	4030-026	
14	Screen Rod Retainer	No longer available	4030-158	
15	Grille Assembly - Upper 36 in.		26637	
16	Hood GCDC60		29575	
17	Grille Assembly - Lower 36 in.		25016	
18	Light Tray Assembly	No longer available	SRV-020	
19	Flame Element Replacement Kit	No longer available	4030-200	
20	Halogen Light	Qty. 2 req.	33961	Y
21	Light Receptacle	No longer available	33962	
22	Snap-in Cord Clip	No longer available	25611	
23	Motor w/Vinyl Cover Assembly	No longer available	4030-883	
24	Back Glass Panel	No longer available	4030-899	
25	Lenticular Lens - 26 in.	No longer available	4030-808	
26	Reflective Flame Decal	No longer available	4021-190	
27	Power Cord	No longer available	4030-802	
28	Hood Clip	Pkg of 24	047-805-24	Y
	Firescreen Ring	Pkg of 10	11857B/10	
	Lava Rock		4021-296	
	Painted Teco-Sil Rock	No longer available	4030-811	
	Screen Handle - HTL logo		SRV10002	
	Strain Relief	No longer available	4030-873	
	Strain Relief Bushing		10203	
	Touch-up Paint - Black		71479	
	Installation Manual		4030-155	