

## OSAGE INDUSTRIES, INC.

| Qty |  | Total       |
|-----|--|-------------|
| 1   | F-550, 193" W.B., 4x4 EST  | \$76,200.00 |
| 1   | Option: Liquid Spring Suspension - <b>Rear Only</b>  | \$14,500.00 |
| 1   | Option: OEM Aluminum Wheels  | \$1,300.00  |
| 1   | <b>Power driver seat and adjustable pedals</b> All 2026 Chassis Will Be Equipped With 17V  |             |
| Qty | <b>SECTION 1 - LED LIGHTS</b>  |             |
| 1   | Whelen Pioneer PFH2 recessed in front of module below condenser  | \$1,750.00  |
| Qty | <b>SECTION 2 - Whelen M-Series Lighting</b>  |             |
| 7   | Whelen M9 LED R, B, A, R/B or R/A  | \$2,940.00  |
| 4   | Whelen M7 LED R, B or A 2 grille on grille guard and 2 front intersection  | \$1,240.00  |
| 14  | Whelen M9 Chrome Flange  | \$420.00    |
| 10  | Whelen M7 or M6 Chrome Flange  | \$250.00    |
| 1   | <b>Lenses Cannot Be Replaced on M Series Lights, Added the New Flanges</b>   |             |
| Qty | <b>SECTION 3 - LIGHT AND LENSES</b>  |             |
| 2   | Cab Reading Light 1/2 Red 1/2 White (Technique)  | \$490.00    |
| 4   | Whelen ION-T Red LED strip lights in rub rails Ref J3417   | \$820.00    |
| Qty | <b>SECTION 4 - SIREN AIR HORNS</b>   |             |
| 1   | Replace face plate for siren heads in cab console 1-Whelen 295, 1-EQ2B   | \$1,239.00  |
| 1   | Replace siren speakers in bumper with new 1 Pair Standard, 1 Pair Federal ES100  | \$870.00    |
| Qty | <b>SECTION 5 - SWITCHPANEL, INVERTER, CHARGES, SHORELINES</b>  |             |
| 1   | Vanner LSC 12-1100 Inverter / Battery Conditioner  | \$1,995.00  |
| 1   | Iota P.C. 30 Battery Charger   | \$335.00    |
| 1   | Kusmaul Auto Eject cover plate only (red)  | \$75.00     |
| 1   | Hidden Switch in Grill for Front Door Unlock (F-Series) includes intermotive lock module   | \$400.00    |
| 1   | Shoreline Indicator at Shoreline   | \$250.00    |
| 1   | Add 110 Outlet (Addition)  | \$190.00    |
| 1   | Add 12 Volt Outlet (ignition Hot)  | \$80.00     |
| 1   | Kusmaull bar graph indicator for charging above shoreline  | \$180.00    |
| 1   | Move antennas from module roof to cab roof, fill in existing holes   | \$300.00    |
| 1   | Replace vista on curb side with 4 pod to match new builds (return existing vista) Ref J3417  | \$650.00    |
| 1   | Re-wire, Re-program Weldon V-Mux System in Existing Truck  | \$650.00    |
| Qty | <b>SECTION 7 - INTERIOR</b>  |             |
|     | Remove Old Flooring, Replace wood sub floor, Inspect Aluminum and repair reseal to exterior. Replace with Seamless one-piece Lon Plate Flooring with New Trim and Cot Mount Plates, Replace stainless sill's & skid tape |             |
| 1   | Specify Color: <u>Grey 157 Flecks</u>  | \$2,900.00  |
| 1   | Spray stainless door sills at side & rear entry with Black rubber liner  | \$250.00    |
| 1   | Sand & Polish Corian Countertop  | \$275.00    |
| 1   | Replace Stainless Steel Kick Plate on Left Wall and Squad Bench  | \$1,750.00  |
| 1   | Replace Stainless Steel drawer face (each)   | \$80.00     |
| Qty | <b>INTERIOR</b>  |             |
| 1   | EVS EMT Seat w/Child Seat and 6-pt Seatbelt w/Base 102 Gunmetal  | \$2,750.00  |

|            |  |             |
|------------|--|-------------|
| 10         | Replace Plexie Glass (per cabinet section)   | \$1,900.00  |
| 1          | Front Console for Type I with Arm Rest and Storage (upgrade)<br>Match current builds <b>Ref J3417</b>  | \$390.00    |
| 1          | Recover all colored pads in Osage box-Vinyl (Doesn't incl. EVS Seat Pads) <b>102 Gunmetal</b>  | \$1,125.00  |
| <u>Qty</u> | <b>INTERIOR</b>  |             |
| 2          | Coat Stainless Grab Rail Yellow (each)   | \$300.00    |
| 4          | Coat Stainless Door Pull Yellow (each)   | \$520.00    |
| 1          | Remove existing south park handle and fill in holes  | \$75.00     |
| 1          | Install new customer supplied Knox Med Vault in current location   | \$150.00    |
| 1          | Reconfigure front wall to match new builds this will delete the 2 Medi kool units and put in one Micro H. The roll up door area will get larger and there will be a cabinet above. Ref drawings for new builds. This will include insatlling new one (1) 12V outlet and one (1) new 110 outlet | \$5,480.00  |
| 1          | Cover up existing suction recess on streetside. Delete the recess from the outside compartment as well and replace shelf with full sized shelf   | \$500.00    |
| <u>Qty</u> | <b>SECTION 8 - COT MOUNTS, STAIR CHAIR, MONITOR BRACKETS</b>   |             |
| 1          | Stryker Power Load   | \$55,000.00 |
| <u>Qty</u> | <b>SECTION 9 - HVAC SYSTEM</b>   |             |
| 1          | Auxiliary condenser mounted on front of box, (if applicable) requires removing interior cabinets (relocate to match new builds and fill in exisiting holes)  | \$2,900.00  |
| 1          | Mermaid Micro H / Micro depth cabient installed in front wall (CONSTANT HOT)   | \$3,800.00  |
| 1          | Engine Driven AC Compressor (Requires Auxiliary condenser Option Also)   | \$4,705.00  |
| 1          | Ac system to be replaced with Danhard 917 equivilant. This includes changing the front condenser to the new style, lowering condenser from curnnet location and insatlling 7 M9's above to match new builds. Fill existing holes and repaint   | \$750.00    |
| <u>Qty</u> | <b>SECTION 10 - MIRROR, HIND-SIGHT, BACKUP CAMERA &amp; SPOTLIGHTS</b>   |             |
| 1          | Remove & Reinstall Reverse Camera (Incl. New Mounting Plate)   | \$175.00    |
| <u>Qty</u> | <b>SECTION 12 - EXTERIOR</b>   |             |
| 1          | Cab Running Board with Grip Strut Inserts  | \$1,350.00  |
| 1          | Rear Step Bumper with Flip-Up Center Section   | \$1,200.00  |
| 1          | Diamond Plate Rear Full Width (stainless not Diamond plate)  | \$425.00    |
| 1          | Diamond Plate Stone Guards Front (pair) (stainless not diamond plate)  |             |
| 1          | License Plate Holder Cast Aluminum (Standard in Package)   | \$120.00    |
| 1          | Zico Retractable Side Entry Step   | \$3,475.00  |
| 1          | Rear Wheel Fender (Pair) Stainless Steel   | \$675.00    |
| 1          | Adjustable Shelf In Exterior Compartment with one Shelf<br><b>#2 Comp Replace Existing With Full Size Shelf</b>  | \$240.00    |
| <u>Qty</u> | <b>EXTERIOR</b>  |             |
| 1          | Dry Deck in all Exterior Compartments (5 Compartments) 6 total   | \$675.00    |
| 10         | Rotary Door Latch each   | \$550.00    |
| 3          | Door Window Hehr Replacement Sliding Glass(each)   | \$630.00    |

|            |  |                    |
|------------|--|--------------------|
| <u>1</u>   | Reflective Tape in Osage Rub Rail Color: <u>  R/W  </u> )  | <u>\$415.00</u>    |
| <u>4</u>   | Aluminum Rub Rails (each) Osage Style  | <u>\$700.00</u>    |
| <u>1</u>   | Cast rear door grabbers (pair) <b>One Pair Standard</b>  | <u>\$200.00</u>    |
| <u>1</u>   | Laverne Black Grill Guard (Prowler)  | <u>\$1,950.00</u>  |
| <u>Qty</u> | <b>EXTERIOR</b>  |                    |
| <u>1</u>   | Truck Number Holders (Painted Box Color) each  | <u>\$550.00</u>    |
| <u>1</u>   | Aluminum Bracket to Hold in Backboards   | <u>\$100.00</u>    |
| <u>1</u>   | DA sand aluminum in 5 exterior compartments and door skins   | <u>\$1,500.00</u>  |
| <u>Qty</u> | <b>SECTION 13 - PAINT, TAPE, LETTERING</b>   |                    |
|            | <b>OSAGE BOX</b> Sandblast all original paint including door jams and repaint with PPG paint (see procedure for details). (Does not include Re-Lettering) <b>151" Box or longer</b> (includes New LED clearance lights, door switches, any bad rotary latches and rusted |                    |
| <u>1</u>   | Nader pins)  | <u>\$19,000.00</u> |
| <u>1</u>   | <b>Paint any color other than White</b> , Includes Red, Yellow, Blue, Silver ect.  | <u>\$1,400.00</u>  |
| <u>1</u>   | Wet-sand and Buff Paint on 151" Box or over  | <u>\$4,050.00</u>  |
| <u>1</u>   | Paint Cab and Box - Two Colors (Door Jams Included)  | <u>\$6,300.00</u>  |
| <u>1</u>   | Paint Box Roof White on Colored Box  | <u>\$950.00</u>    |
|            | 6" 3M Reflective Diamond Grade Chevrons, Two Alternating Color   |                    |
| <u>1</u>   | Around Doors   | <u>\$3,275.00</u>  |
| <u>3</u>   | Add Two-Color, 6" Reflective Bottom of Entry Door, each (18" Tall)   | <u>\$600.00</u>    |
| <u>1</u>   | Labor To Remove Old Chevrons From Entry Door Panels  | <u>\$150.00</u>    |
| <u>1</u>   | 6" Chevron Diamond Grade Two Colors Rear Doors   | <u>\$1,540.00</u>  |
| <u>1</u>   | Graphics to match layout for new builds Hall County  | <u>\$4,887.00</u>  |
| <u>1</u>   | Repaint interior aluminum cabinets marble stone  | <u>\$12,700.00</u> |