

Existing Garage



Corner of  
Addition

Property  
Line


↓  
Street View

↓ House Lot 33

Property  
Line




Corner of  
Addition



← Building Addition Site







Existing Building

Not at the top of the hill that drops down

Corner marker

Trees fallen on existing garage - siding was repaired. Gutters have not been repaired



Exposed roots  
on trees

