



## Mini Stainless Steel IMOB, Lead Free Qtr-turn Arrester Valve, 1/2" Sweat Connection





Ice Maker Box Installation Instructions				
) Remove the faceplate that is attached to the ice maker box and save for future installation.				
?) Using either nails or screws, mount the box to the stud via the flanges on the side of the box.				
3) Box can be mounted:				
a) On either side of the stud bay.				
b) At a height determined by builder/installer.				
c) In any direction - top mount, etc.				
l) Connect the copper water supply tubing to the ice maker box valve via sweat/solder connection.				
5) Check all local codes for appropriate approvals and requirements.				
b) To the 1/4" outlet of valve attach either:				
a) Copper supply tubing via compression connection.				
b) Poly supply tubing via compression connection - brass insert into poly tube is required				
c) Braided hose via threaded connection.				
7) Connect to the inlet connection of the refrigerator.				

Part #	<b>Replacement Component Description</b>	Qty
88366	Lead Free Quarter Turn Sweat Ice Maker Valve w/HA	1
89917	Locknut for Solder Valve	1
90193	Valve Spacer	1

Part #	Replacement Component Description	Qty
97151	Faceplate	1
90159	Faceplate Screws (4-pack)	1

Item #	Replacement Component Description	Model #	Case Qty	Packaging
88525	Mini Stainless Steel IMOB, Lead Free Qtr-turn Arrester Valve, 1/2" Sweat Connection	SSMIB6AB	5	Standard Pack



500 Distribution Parkway, Collierville, TN 38017 = Phone: 800-888-8312 = Fax: 901-853-5008 = www.ipscorp.com