

How to Free Standing Lace



Materials

:
WOVEN WSS

Top thread matching bobbin(s)

Bowl of warm water

Step 1: DO NOT BE AFRAID – this is the easiest thing EVER! **YOU DO want to use the WOVEN type of WSS!!!** Hoop EITHER 1 piece OR 2 pieces if you are paranoid, so that there are no wrinkles and it is firm BUT NOT SUPER TIGHTLY STRETCHD.

Step 2: Spin up matching bobbins of top thread – 4x4 patterns take ABOUT ½ a bobbin, 5x7s take about a full bobbin. USE your color matched bobbin for EVERY color stop.

Step 3: Run all color stops, changing bobbins for each DIFFERENT color

Step 4: When all stitching is complete, carefully cut project out of hoop, about 1/8" away from the stitching to remove excess WSS



Step 5: Soak project in warm water for 15-20 minutes to remove remaining WSS.

Step 6: Remove from water bath and pat dry on flat surface. Air dry to remove remaining water.

*IF You want your FSL STIFFER you can use a stiffener, spray starch and medium iron, or Modge Podge.

See? STUPID EASY!



Be sure to check out our YouTube channel:
<https://www.youtube.com/c/StringTheoryFabricArt>

Our store: <https://stringtheoryfabricart.com/>

AND our Facebook Fan Group where you will find more helpful hints, discounts, and coupons:
<https://www.facebook.com/groups/STFAGroup/>