

CROSS / CUT Mod.3804 B

2x15mm

01.07.2012

4010 145

4010 167

9006 087

4010 128

4010 416

4010 167

2630 008

4010 031

4010 265

4010 032

4010 032

4010 031

4010 042

9002 944

9002 180

4010 140

4010 068

4010 125

2201 037

4010 045

9002 497

9005 647

9002 497

9001 613

9002 944

2202 041

4010 362/100V

4010 361/120V

4010 360/230V

9002 942

4010 300/115V
4010 299/230V

9002 944

9002 684

9100 425

9002 944

9100 421

9002 684

4010 072

4010 120

4010 164

9003 763

4010 192

9003 763

4010 164

9002 896


9003 763

4010 120

9003 763

9002 896

9003 763




Mod. 3804 B

CROSS / CUT

2x15mm


01.07.2012




Mod.3804 B
 CROSS / CUT
 2x15mm
 01.07.2012

Mod. 3804 B

CROSS / CUT
2x15mm
01.07.2012



Lastteil Power part
100/115V: 4010 300
230V: 4010 299



Mod. 3804 B
CROSS / CUT
2x15mm
01.07.2012


Stromlaufplan 3804 B
schema de
circuit ectrique 3804 B
wiring diagram 3804 B

4010 843

CROSS / CUT Mod. 3804 B 2x15mm


01.07.2012

Anschlußplan 3804 CROSS/CUT B
Diagramme de branchement 3804 CROSS/CUT B
Connecting diagram 3804 CROSS/CUT B




Mod.3804 B

01.02.2013



CROSS / CUT 4x40mm
Mod.3804 B
 01.02.2013



CROSS / CUT 2x15mm
Mod.3804 B
 01.02.2013

