




# Mod.4000 E

01.06.1998






**CROSS / CUT**  
**Mod. 4000 E**  
 4x60mm  
 01.06.1998



**CROSS / CUT**  
**4x60mm**  
**Mod. 4000 E**  
 01.06.1998

# Mod.4000 E


01.06.1998




CROSS / CUT 4x60mm  
**Mod.4000 E**

01.06.1998

220-240V



CROSS / CUT 4x60mm  
**Mod.4000 E**  
 01.06.1998  
 100-115V



9003 842

9001 737

9001 534

9001 396

3102 080

9001 395

9001 533

9003 012

4004 370

4004 065

9000 044

9003 190

9003 292

9001 906

4004 364

4004 062

9002 592

4000 0100

9003 047


9000 465

9002 933



9003 275

9000 410


4004 067



CROSS / CUT 4x60mm  
**Mod. 4000 E**  
 01.06.1998



Anschlußplan 4000 E CROSS/CUT  
Diagramme de branchement 4000 E CROSS/CUT  
Conecting diagram 4000 E CROSS/CUT




CROSS / CUT 4x60mm



Mod. 4000 E

01.06.1998

220-240V




Anschlußplan 4000 E CROSS/CUT  
 Diagramme de branchement 4000 E CROSS/CUT  
 Conecting diagram 4000 E CROSS/CUT



**Mod. 4000 E**

CROSS / CUT 4x60mm

01.06.1998  
 100-115V




4000 118  
10

Stromlaufplan 4000 E CROSS/CUT  
 schéma de 4000 E CROSS/CUT  
 circuit électrique 4000 E CROSS/CUT  
 wiring diagram 4000 E CROSS/CUT

CROSS / CUT 4x60mm  
**Mod. 4000 E**  
 01.06.1998  
 220-240V

Stromlaufplan 4000 E CROSS/CUT  
 schéma de 4000 E CROSS/CUT  
 circuit électrique 4000 E CROSS/CUT  
 wiring diagram 4000 E CROSS/CUT



**Mod. 4000 E**


CROSS / CUT 4x60mm

01.06.1998


220-240V

4000 851  
 11

Stromlaufplan 4000 E CROSS/CUT  
 schéma de 4000 E CROSS/CUT  
 circuit électrique 4000 E CROSS/CUT  
 wiring diagram 4000 E CROSS/CUT



**Mod. 4000 E**  
 CROSS / CUT  
 4x60mm  
 01.06.1998  
 100-115V



100-115V

01.06.1998

# Mod. 4000 E

CROSS / CUT 4x60mm

4000 124  
13

Stromlaufplan 4000 E CROSS/CUT  
 schéma de 4000 E CROSS/CUT  
 circuit électrique 4000 E CROSS/CUT  
 wiring diagram 4000 E CROSS/CUT