## OSAGE INDUSTRIES, INC.

Qty		Total
<u> 1</u>	F-550, 193" W.B., 4x4 EST	\$76,200.00
<u></u>	Option: Liquid Spring Suspension - Rear Only	\$14,500.00
<u>1</u>	Option: OEM Aluminum Wheels	\$1,300.00
1	Power driver seat and adjustable pedals All 2026 Chassis Will Be Equi	pped With 17V
Qty _	SECTION 1 - LED LIGHTS	
<u> </u>	Whelen Pioneer PFH2 recessed in front of module below condenser	<u>\$1,750.00</u>
<u>Qty</u> _	SECTION 2 - Whelen M-Series Lighting	
<u> 7</u>	Whelen M9 LED R, B, A, R/B or R/A	<u>\$2,940.00</u>
<u>4</u>	Whelen M7 LED R, B or A 2 grille on grille guard and 2 front	\$1,240.00
	intersection	
14	Whelen M9 Chrome Flange	\$420.00
<u>10</u>	Whelen M7 or M6 Chrome Flange	<u>\$250.00</u>
1	Lenses Cannot Be Replaced on M Series Lights, Added the New Flanges	
Qty _	SECTION 3 - LIGHT AND LENSES	<b>*</b> 400.00
<u>2</u>	Cab Reading Light 1/2 Red 1/2 White (Technique)	\$490.00
4	Whelen ION-T Red LED strip lights in rub rails Ref J3417	<u>\$820.00</u>
<u>Qty</u>	SECTION 4 - SIREN AIR HORNS	
<u>1</u>	Replace face plate for siren heads in cab console 1-Whelen 295, 1-EQ2B	\$1,239.00
<u>1</u>	Replace siren speakers in bumper with new 1 Pair Standard, 1 Pair Federal ES100	\$870.00
	SECTION 5 - SWITCHPANEL, INVERTER, CHARGES,	
<u>Qty</u>	SHORELINES	
1	Vanner LSC 12-1100 Inverter / Battery Conditioner	\$1,995.00
<del>_</del>	lota P.C. 30 Battery Charger	\$335.00
<del>_</del>	Kussmaul Auto Eject cover plate only (red)	\$75.00
<del>_</del> _	Hidden Switch in Grill for Front Door Unlock (F-Series) includes	
<u>1</u>	intermotine lock module	<u>\$400.00</u>
<u> </u>	Shoreline Indicator at Shoreline	\$250.00
<u> </u>	Add 110 Outlet (Addition)	\$190.00
1	Add 12 Volt Outlet (ignition Hot)	\$80.00
<u> </u>	Kussmaull bar graph indicator for charging above shoreline	\$180.00
1	Move antennas from module roof to cab roof, fill in existing holes	\$300.00
	Replace vista on curb side with 4 pod to match new builds (return	<u></u>
<u>1</u>	existing vista) Ref J3417	<u>\$650.00</u>
<u>1</u>	Re-wire, Re-program Weldon V-Mux System in Existing Truck	<u>\$650.00</u>
Qty	SECTION 7 - INTERIOR	
	Remove Old Flooring, Replace wood sub floor, Inspect Aluminum	
	and repair reseal to exterior. Replace with Seamless one-piece	
	Lon Plate Flooring with New Trim and Cot Mount Plates, Replace	
	stainless sill's & skid tape	
<u>1</u>	Specify Color:Grey 157 Flecks	\$2,900.00
<u>1</u>	Spray stainless door sills at side & rear entry with Black rubber liner	\$250.00
1	Sand & Polish Corian Countertop	\$275.00
<u> </u>	Replace Stainless Steel Kick Plate on Left Wall and Squad Bench	<u>\$1,750.00</u>
<u> </u>	Replace Stainless Steel drawer face (each)	\$80.00
Qty	INTERIOR	
<u>1</u>	EVS EMT Seat w/Child Seat and 6-pt Seatbelt w/Base 102 Gunmetal	<u>\$2,750.00</u>
	·	<del></del> _

<u>10</u>	Replace Plexie Glass (per cabinet section)	\$1,900.00
1	Front Console for Type I with Arm Rest and Storage (upgrade)	\$390.00
	Match current builds Ref J3417	<u>ψ390.00</u>
<u>1</u>	Recover all colored pads in Osage box-Vinyl (Doesn't incl. EVS Seat	\$1,125.0 <u>0</u>
	Pads) 102 Gunmetal	<u>ψ1,123.00</u>
<u>Qty</u>	INTERIOR	
<u>2</u>	Coat Stainless Grab Rail Yellow (each)	<u>\$300.00</u>
<u>4</u>	Coat Stainless Door Pull Yellow (each)	<u>\$520.00</u>
<u> </u>	Remove existing south park handle and fill in holes	<u>\$75.00</u>
<u> </u>	Install new customer supplied Knox Med Vault in current location	<u>\$150.00</u>
<u>1</u>	Reconfigure front wall to match new builds this will delete the 2 Medi kool units and put in one Micro H. The roll up door area will get larger and there will be a cabinet above. Ref drawings for new builds. This will include insatlling new one (1) 12V outlet and one (1) new 110 outlet	<u>\$5,480.00</u>
	Cover up existing suction recess on streetside. Delete the recess	
<u>1</u>	from the outside compartment as well and replace shelf with full	<u>\$500.00</u>
	sized shelf	
Qty	SECTION 8 - COT MOUNTS, STAIR CHAIR, MONITOR BRACKETS	
<u>1</u>	Stryker Power Load	\$55,000.00
Qty	SECTION 9 - HVAC SYSTEM	
	Auxiliary condenser mounted on front of box, (if applicable)	
<u>1</u>	requires removing interior cabinets (relocate to match new builds	<u>\$2,900.00</u>
	and fill in exisiting holes)	
<u>1</u>	Mermaid Micro H / Micro depth cabient installed in front wall	\$3,800.00
	(CONSTANT HOT)	ψο,οοο.οο
<u>1</u>	Engine Driven AC Compressor (Requires Auxiliary condenser Option Also)	<u>\$4,705.00</u>
	Ac system to be replaced with Danhard 917 equivilant. This	
	includes changing the front condenser to the new style, lowering	4=== 0.0
<u>1</u>	condernser from currnet location and insatlling 7 M9's above to	<u>\$750.00</u>
	match new builds. Fill existing holes and repaint	
	SECTION 10 - MIRROR, HIND-SIGHT, BACKUP CAMERA &	
<u>Qty</u>	SPOTLIGHTS	
<u>1</u>	Remove & Reinstall Reverse Camera (Incl. New Mounting Plate)	\$175.00
Qty	SECTION 12 - EXTERIOR	
	Cab Running Board with Grip Strut Inserts	\$1,350.00
1	Rear Step Bumper with Flip-Up Center Section	\$1,200.00
1	Diamond Plate Rear Full Width (stainless not Diamond plate)	\$425.00
<u> 1</u>	Diamond Plate Stone Guards Front (pair) (stainless not diamond plate	
<u>1</u>	License Plate Holder Cast Aluminum (Standard in Package)	\$120.00
<u>1</u>	Zico Retractable Side Entry Step	\$3,475.00
<u> </u>	Rear Wheel Fender (Pair) Stainless Steel	\$675.00
1	Adjustable Shelf In Exterior Compartment with one Shelf	
<u>1</u>	#2 Comp Replace Existing With Full Size Shelf	\$240.00
Qty	EXTERIOR	
<u>1</u>	Dry Deck in all Exterior Compartments (5 Compartments) 6 total	<u>\$675.00</u>
	· · · · /	
<u>10</u>	Rotarary Door Latch each	<u>\$550.00</u>

<u>1</u>	Reflective Tape in Osage Rub Rail Color:R/W)	<u>\$415.00</u>
<u>4</u>	Aluminum Rub Rails (each) Osage Style	<u>\$700.00</u>
<u>1</u>	Cast rear door grabbers (pair) One Pair Standard	<u>\$200.00</u>
<u>1</u>	Laverne Black Grill Guard (Prowler)	<u>\$1,950.00</u>
Qty	EXTERIOR	
<u>1</u>	Truck Number Holders (Painted Box Color) each	<u>\$550.00</u>
<u> </u>	Aluminum Bracket to Hold in Backboards	\$100.00
<u> </u>	DA sand aluminum in 5 exterior compartments and door skins	\$1,500.00
<u>Qty</u>	SECTION 13 - PAINT, TAPE, LETTERING	
	OSAGE BOX Sandblast all original paint including door jams and	
	repaint with PPG paint (see procedure for details). (Does not	
	include Re-Lettering) 151" Box or longer (includes New LED	
	clearance lights, door switches, any bad rotary latches and rusted	
<u>1</u>	Nader pins)	<u>\$19,000.00</u>
1	Paint any color other than White, Includes Red, Yellow, Blue,	\$1,400.00
	Silver ect.	<u>ψ1,+00.00</u>
<u> </u>	Wet-sand and Buff Paint on 151" Box or over	<u>\$4,050.00</u>
<u>1</u>	Paint Cab and Box - Two Colors (Door Jams Included)	<u>\$6,300.00</u>
<u> </u>	Paint Box Roof White on Colored Box	<u>\$950.00</u>
	6" 3M Reflective Diamond Grade Chevrons, Two Alternating Color	
<u> </u>	Around Doors	<u>\$3,275.00</u>
<u>3</u>	Add Two-Color, 6" Reflective Bottom of Entry Door, each (18" Tall)	<u>\$600.00</u>
<u>1</u>	Labor To Remove Old Chevrons From Entry Door Panels	<u>\$150.00</u>
<u></u>	6" Chevron Diamond Grade Two Colors Rear Doors	\$1,540.00
<u> </u>	Graphics to match layout for new builds Hall County	\$4,887.00
<u>1</u>	Repaint interior aluminum cabinets marble stone	<u>\$12,700.00</u>