



Georgia Department of Public Health On-Site Sewage Management System Performance Evaluation Report Form

APPLICANT NAME: CLYDE MORRIS	PROPERTY/SYSTEM ADDRESS: 2375 WHIPPOORWILL LN GAINESVILLE, GA 30501	EVALUATION ID: 030990
APPLICANT PHONE: [REDACTED]		COUNTY: Hall
APPLICANT EMAIL ADDRESS: [REDACTED]	SUBDIVISION/LOT/BLOCK: C H CONNER/4/.	REASON FOR EVALUATION: Structure Addition
Inspection Records		
No	1. Inspection records exist for this septic system.	
No	2. Inspection records indicate that all components of the septic system were properly constructed and approved at the time of original inspection. A copy of the original inspection report is attached.	
Maintenance Records (applicable copies are attached)		
No	3. Maintenance or installation records indicate that the tank has been pumped out or installed within the past 5 years. Note: it is recommended that septic tanks be pumped at least once every 5 years.	
N/A	4. Systems with aerobic treatment unit(s) (ATU): Records indicate the ATU has been serviced in accordance with the manufacturer's recommended maintenance schedule OR an authorized representative of the manufacturer has provided documentation that the ATU is operating sufficiently.	
N/A	5. Systems with grease trap(s): Maintenance records indicate the grease trap(s) has been pumped out within the last 6 months OR documentation has been provided by a qualified individual confirming that the grease trap contains less than 75% of the designed grease holding capacity and is operating sufficiently.	
System Assessment and Existing Site Conditions (applicable copies are attached)		
No	6. The septic tank was uncovered at the time of this County Board of Health Evaluation OR maintenance records exist and the tank appears to meet the required design, construction, and installation criteria. The appropriateness of the sizing and installation criteria of the absorption field cannot be verified since no initial inspection records exist.	
No	7. A Georgia certified septic tank installer has provided written documentation of the system design, location, and components.	
Yes	8. This site evaluation by the County Board of Health revealed no evidence of system failure.	
No	9. This site evaluation by the County Board of Health revealed no evidence of adverse conditions which would affect the functioning of the system.	
Addition to Property		
No	10. This site evaluation as well as the provided information indicate that the proposed construction to the home or property should not adversely affect the functioning of the existing system.	
Relocation of Home or Change of Use		
N/A	11. This site evaluation as well as the provided information indicate that the system appears to meet the required design, construction, and installation criteria to accommodate the proposed relocation of the home or change of use for the facility should not adversely affect the functioning of the existing system.	

See 2nd page for evaluation notes, disclaimer, and signature.

Performance Evaluation Report Form (continued)

PROPERTY/SYSTEM ADDRESS: 2375 WHIPPOORWILL LN GAINESVILLE, GA 30501	EVALUATION ID: 030990
	SUBDIVISION/LOT/BLOCK: C H CONNER/4/.

Adverse Conditions (i.e. malfunctioning or damaged system or clear evidence of a condition, or conditions, that would likely contribute to system malfunction or unacceptable risk to public health):

TANK LOCATED WITHING 1FT OF PROPOSED CAR PORT.

Additional Notes/Comments:

SEE ADVERSE CONDITIONS

PROPOSED CARPORT 36'X9'X14' ON EXISTING GRAVEL DRIVEWAY.

NO ADDITIONAL BDRMS PERMITTED.

KEEP CARPORT AT LEAST 5' FROM SEPTIC TANK AND 5' FROM DRAIN LINES. IF THE SEPTIC SYSTEM SHOULD BE DAMAGED FROM THE CONSTRUCTION, THE HOMEOWNER WILL BE REQUIRED TO GET A REPAIR PERMIT AND REPAIR THE SYSTEM.

Inspector:
Colin Baker

Signature:




Date:
11/25/2025

I verify the above information to be correct at the date and time of this evaluation only. **Disclaimer:** This verification shall not be construed as a guarantee of the proper functioning of this system for any given period of time. No liability is assumed for future damages that may be caused by system malfunction.

Inspector/Date: 11/25/25 e.B

Permit #:
Septic Tank:
Filter:
ATU:
Pump Tank:
Pump:
D-Box:
ATD:
Type of Line:
Total LF:

Eval, not inspection
Eval # 030990



ARE ABOVE GROUND
ME OF SURVEY

N/F GARNETT

DB 1574, pg 244
DB 1631, pg 195
DB 1637, pg 132
PB 66, pg 78

P/L AS DETERMINED FROM DB 9315, pg 573 AND
AS SHOWN ON A SURVEY FOR CLYDE Y. MORRIS,
JR., DATED MAY 30, 2001

USACOE
MONUMENT
FOUND

RAIL ROAD
SPIKE FOUND

N 49°46'03"E
20.63'
APPROX. SEPTIC

N 88°19'11"E 45.19'

SEPTIC CLEAN OUT

*SEPTIC MARKERS
PROPOSED GARPORT

P/L AS DESCRIBED
IN DB 1631, pg 195
& DB 1637, pg 132
AND AS SHOWN ON
PB 66, pg 78

SEPTIC CLEAN OUT

USACOE
MONUMENT
FOUND

STEPS

PORCH

WALK WAY

HOUSE

0.075 ACRE

*SEPTIC MARKERS

N 15°20'14"W 45.90'

PORCH

WHIPPOORWILL LANE
SHOWN AS 18' R/W ON PB 66, pg 78
14' ASPHALT

S 08°14'03"E 53.64'

~GRAVEL~

NAIL FOUND

USACOE
MONUMENT
FOUND

S 84°06'26"W 56.76'

IPF 1/2" RB
0.7' SW

WOOD RETAINING WALL

5'

N/F POWERS
DB 7734, pg 59

S 17°12'15"W 1004.87' TO
THE C/L INTERSECTION OF
WHIPPOORWILL LANE &
SPORTSMAN CLUB ROAD

SURVEY FOR:
CLYDE Y. MORRIS, JR.

2375 Whipoorwill Lane

LAND LOT 161
9th DISTRICT
HALL COUNTY, GEORGIA


FIELD DATE(S): 7/9/2024
10/6/2025

PLAT DATES: 10/6/2025



GRAPHIC SCALE
1 INCH = 10 FEET

PROJECT No. 24-0



2375

Property Line
WHIPPOORWILL LANE.

